

DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 11/08/2012  
FORM APPROVED  
OMB NO. 0938-0391

45th 12/22/12

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  445383	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 B. WING _____	(X3) DATE SURVEY COMPLETED  11/05/2012
---	---	--	---

NAME OF PROVIDER OR SUPPLIER

HORIZON HEALTH AND REHAB CENTER

STREET ADDRESS, CITY, STATE, ZIP CODE

811 KEYLON STREET  
MANCHESTER, TN 37355

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K 025 SS=E	<p><b>NFPA 101 LIFE SAFETY CODE STANDARD</b></p> <p>Smoke barriers are constructed to provide at least a one half hour fire resistance rating in accordance with 8.3. Smoke barriers may terminate at an atrium wall. Windows are protected by fire-rated glazing or by wired glass panels and steel frames. A minimum of two separate compartments are provided on each floor. Dampers are not required in duct penetrations of smoke barriers in fully ducted heating, ventilating, and air conditioning systems. 19.3.7.3, 19.3.7.5, 19.1.6.3, 19.1.6.4</p> <p>This STANDARD is not met as evidenced by: Based on observation, it was determined the facility failed to maintain the fire/smoke walls.</p> <p>The finding included:</p> <p>On 11/5/12 at 1:20 PM, observation within the ceiling area above the 400 hall next to the egress door revealed an open ended (1/2") one-half inch diameter electrical conduit.</p> <p>The finding was acknowledged by the Administrator and verified by the Maintenance Director during the exit interview on 11/5/12.</p>	K 025	<p>The opening in the 400 hall firewall has been closed utilizing fire-resistant caulking material around the conduit passing through the wall.</p> <p>The Maintenance Director will inspect all firewalls on a quarterly basis as part of regularly scheduled life safety inspections.</p>	
K 038 SS=E	<p><b>NFPA 101 LIFE SAFETY CODE STANDARD</b></p> <p>Exit access is arranged so that exits are readily accessible at all times in accordance with section 7.1. 19.2.1</p>	K 038		

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

*Jeffrey Gaddis, LNA* ADMINISTRATOR 11/20/12

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 11/08/2012  
FORM APPROVED  
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>445383</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING <b>01 - MAIN BUILDING 01</b> B. WING _____		(X3) DATE SURVEY COMPLETED  <b>11/05/2012</b>
NAME OF PROVIDER OR SUPPLIER  <b>HORIZON HEALTH AND REHAB CENTER</b>			STREET ADDRESS, CITY, STATE, ZIP CODE <b>811 KEYLON STREET MANCHESTER, TN 37355</b>		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 038	Continued From page 1  This STANDARD is not met as evidenced by: Based on testing and observation, it was determined the facility failed to maintain the fire exit doors.  The finding included:  On 11/5/12 at 11:35AM, testing of the memory care exit door revealed the door failed to open within (15) fifteen seconds.  The finding was acknowledged by the Administrator and verified by the Maintenance Director during the exit interview on 11/5/12.	K 038	K038 The secured exit door sensor has been repaired to open within 15 seconds of activation. These doors will be added to the scheduled weekly inspection schedule to assure that the sensor has not been damaged or otherwise inactivated.		